



“Numerare al mm”, numerando i mm.




Studio sulla visibilita' dovuta a diverso spessore
delle tacche.












“Numerare al mm”, numerando i mm.



“Numerare al mm”, numerando i mm.



“Numerare al mm”, numerando i mm.

		
1cm:2 1mm:0,2	0 2 4 6 8 10 12 14 16 18 20 22 24	
0  2	0 0,2 0,4 0,6 0,8 1 1,2 1,4 1,6 1,8 2	
2  4	2 2,2 2,4 2,6 2,8 3 3,2 3,4 3,6 3,8 4	
4  6	4 4,2 4,4 4,6 4,8 5 5,2 5,4 5,6 5,8 6	
6  8	6 6,2 6,4 6,6 6,8 7 7,2 7,4 7,6 7,8 8	
8  10	8 8,2 8,4 8,6 8,8 9 9,2 9,4 9,6 9,8 10	
10  12	10 10,2 10,4 10,6 10,8 11 11,2 11,4 11,6 11,8 12	
12  14	12 12,2 12,4 12,6 12,8 13 13,2 13,4 13,6 13,8 14	
14  16	14 14,2 14,4 14,6 14,8 15 15,2 15,4 15,6 15,8 16	
16  18	16 16,2 16,4 16,6 16,8 17 17,2 17,4 17,6 17,8 18	
18  20	18 18,2 18,4 18,6 18,8 18 19,2 19,4 19,6 19,8 20	